Section A. Facility Data		
Facility No.	Buildings 120, 120A, S120 (Bus Stop), 920 and 920A	
Facility Descriptor:	East and West Access Posts, Vehicle Search Facilities	
Project:	RISS – Area 5 Group 15 D&D	
Date of Demolition:	6/29/05 (120) and 4/27/05 (920)	
Additional Information:	Guard posts and portable shelters demolished and disposed of as sanitary waste.	
(Must include information on environmental releases and conditions of site at turnover to Environmental Restoration)		

Section B. Final Characterization Data		
Reconnaissance Level Characterization Report	Reconnaissance Level Characterization Report –	
(concurrence received)	Concurrence, Steven H. Gunderson to Joseph A. Legare,	
	dated July 18, 2005.	
In-process Characterization	N/A	
Pre-Demolition Survey Report (approval received)	N/A	
Post-Demolition Survey Report (as necessary)	N/A	

Canitamy Dianocal			
Sanitary Disposal Disposal Site:	BFI Foothills Landfill, Golden, Colorado		
Waste Volume (m³):	6,900 Cubic yards		
Waste Weight (tons):	5,157.7 net tons		
Maste Weight (tons): Additional Information:	Above grade building debris		
Additional Information.	Above grade building debris		
Hazardous Disposal			
Disposal Site:	Kettleman Hills Facility, Kettleman City, CA, Bethlehem Apparatus Co, Hellertown, PA or Onyx, Henderson, CO.		
Waste Volume (m³):	Minor amounts		
Additional Information:	Electronic circuit boards, thermostats, exit signs, batteries, fluorescent light bulbs and any other RCRA hazardous components were removed and taken to the RFCA temporary unit for combination with like waste streams for disposal.		
TSCA Waste Disposal			
Disposal Site:			
Waste Voiume (m³):	N/A		
Additional Information:			
Asbestos Waste Disposal Disposal Site:			
Waste Volume (m³):	N/A		
Additional Information:			
Low-Level Waste Disposal Disposal Site:			
Waste Volume (m³):	N/A		
Additional Information:	·		
Low-Level Mixed Waste Disposal Disposal Site:			
Waste Volume (m³):	N/A		
Additional Information:			
Recycled Material Recycle Facility: Waste Volume (m³):			
Additional Information:			

Type 1 Facility Closeout Report

Property Disposition Receiver Locations (major items only):	N/A	
Volume (m³):		,
Weight (tons):		
Additional Information:		
	\mathcal{M}	
Section D. Approvals Kaiser-Hill Project Manager	Calle	8/1/05
Name/Stg	pature	7 7 Date

Additional Facility Information

Buildings 120 and 920 were each 560 square-foot Guard Posts located at the west and east access gates, respectively. The buildings were constructed with concrete walls, concrete foundation, and an insulated metal roof. Each building was connected to the vehicle access gates and the control equipment for the access gates.

Each of the buildings had the following utilities: electrical, potable water, and sanitary drains. The buildings were equipped with external emergency diesel generators, including a diesel fuel tank.

Buildings 120A and 920A were 120 square-foot wooden, skid-mounted portable shelters used as general offices and break rooms for site security personnel. The 120A and 920A shelters were located at the west and east Vehicle Search Facilities, respectively. Buildings 120A and 920A were equipped with electricity.

Buildings 120, 120A, 920 and 920A were removed during D&D activities, and sent offsite for disposal. The utilities were disconnected and removed to at least three feet below final grade as indicated on the attached map. There are no remaining structural components, utility lines, or parts of the foundation. The buildings are not in an IHSS or PAC therefore no soil sampling is required.



